



Aerial image of upstream wetland with prograding delta of fine sediment.



Aerial image of wetlands 2 and 1 (looking upstream) with previous canalised channel alignment still evident



Wetland 1 before and after connection with main channel through implementation of the restoration works



Wetland 1 under low flow conditions in Nov 2018