


Changes to Chiswick Eyot over Time.



Chiswick Eyot is a small island in the Thames near London, England. It has been subject to modification and restoration work over many years as well as natural erosion processes.

Over time it is possible to see that the island has generally declined in area. It has migrated between the west and east bank. The north end has retreated significantly while the southern end has been restored somewhat following the separation of a small island.

Map compiled by Martin Richardson.

The data was obtained from Ordnance Survey in the UK. The maps use the UK National Grid.